Work Orde Thursday, July 0							1			!	Page 1
Revision ID:	D4132-3 Gasket			Accept				s	etup Stai		144   144   114 144   14   16   16
	7/1/2010	Start Qty: 4.00 Req'd Qty: 4.00	1881/1 8181 1886   1881/1 8181 1881		Cust Item ! Customer:	ID:	n H				
Approvals:	Process Pla	n:	Date/D-7-0/	Tooling: SPC (Y/N):		ate:	- 	R	Run Star Sto		9118 181 1181 1888 Úire 188 1181 1881
Sequence ID/ Work Center ID	)	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Rev	ision Nbr									*· = • · · · · · · · · · · · · · · · · ·
D4132	A				,						z L
100   <b>                               </b> Waterjet		FLOW WATER JET  Memo		0.00	1			M	18	01	14 4
FLOW CNC Waterje	et		<u>.A.</u>	0.00							1
		QC2- Inspect parts off r	machine FAI/FAIB	0.00				M	10	. 07	. 14 (2
QC Quality Control		Memo		0.00					_10	. 07	· _//
		•				•					
120		QC8- Inspect parts - sec	cond check	121	osliu				`		
QC		Memo		0.00	V + 114			47	)		<del></del>

Quality Control

W/O:			W	· ·	•					
DATE	STEP	PRO	OCEDURE CH	ANGE		Ву	Date	Qty	Chief Eng /	Approval QC Inspector
,								1	Prod Mgr	, , , ,
					ļ					
							+			
										3
Part No	•	PAR #:	Fault Ca	tegory:	_ NCF	R: Yes I	No DQA:		Date: _	
	Re	esolution:	Disposit	ion:	QA:	N/C Clo	sed:		Date: _	
NCR:		,	WORK OR	DER NON-CONFORM	ANCE	(NCR				
DATE	OTED	Description of NC			ion B		Verifica	ion	Approval	Approval
DATE	STEP	Section A								QC Inspector
7		<u> </u>								
										į
l										
					:					
	1 1		1				}		I	1

### Work Order ID 60303

Thursday, July 01, 2010 1:09:42 PM



Page 2

Item ID:

D4132-3

Accept

Setup Start

Stop



**Revision ID:** 

Item Name:

Gasket

**Start Date:** 

7/1/2010

Start Qty: 4.00

Required Date: 7/8/2010

Req'd Qty: 4.00



**Cust Item ID:** Customer:

Reference:

Approvals:

Process Plan:

Date:

Date:

**Tooling:** 

SPC (Y/N):

Date:

Tool ID

Date:

Code

Tool # Plan

Stop

Reject

Qty

Run

Accept

Qty



Insp.

Stamp

Reject

Number

Sequence ID/ Work Center ID

130

140

Packaging Packaging

Operation Description

Identify as per dwg & Stock Location:

0.00

Set Up/

Run Hours

0.00

QC21- Final Inspection - Work Order Release

QC

Quality Control

Memo

Memo

0.00

0.00

<b>Dart Aeros</b>	pace Ltd
-------------------	----------

		W	ORK ORDER CH	IANGES			ł		Ì	
DATE	STEP	PRO	OCEDURE CH	ANGE		Ву	Date	City	Approval Chief Eng /	Approval QC Inspector
									Prod Mgr	QO MOPOCION
-				A. L.						
Part No		PAR #:	Fault Cat	egory:	NO	CR: Yes	No <b>DQA</b> :		_ Date: _	
	R	esolution:	Dispositi	on:	Q.	A: N/C CI	osed:	<u> </u>	Date: _	
NCR:			WORK ORI	DER NON-CONF	ORMANC	E (NCR	)			
DATE	STEP	Description of NC		Corrective Action	Section B	0:	Verifica		Approval	Approval
DATE	SILF	Section A	Initial Chief Eng	Action Descri Chief Eng	ption	Sign & Date	Section	C	Chief Eng	QC Inspector
			,							
								İ		

### **Picklist Print**

Thursday, July 01, 2010 1:09:47 PM

Work Order ID: 60303

Parent Item:

D4132-3

Parent Item Name: Gasket



**Start Date: 7/1/2010** 

Required Date: 7/8/2010

Start Qty: 4.00


Required Qty: 4.00

$C_{0}$	mn	en	te•


IPP Rev:A 10.06.24 new issue DD verf:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
MNEO60S.063		Purchased	No			100	sf	364.8531	1.0446	4.398316			
NEOPRENE SHEET 0.063				<u>Location</u> MAT	Į.	<u>Loc Q</u>	9.6	Loc Code	i		m	10.	07.14
				WAI	114691		i9.6 '				. (	, -	.,.,
				MAT052	114176	105.25 105.25			ь				


		·								
W/O:			WC	ORK ORDER CHANG	ES					•
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	(	ty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Ye	s No <b>DQ</b>	A:		_ Date: _	
·		esolution:	Disposition	n:	_ QA: N/C	Closed:			Date: _	
NCR:		,	WORK ORD	ER NON-CONFORM	ANCE (NO	R)				
DATE	STEP	Description of NC			ion B Sigr	Verifi			Approvai	Approval
	J.L.	Section A	Initial Chief Eng	Action Description Chief Eng	Da		ion	C ——	Chief Eng	QC Inspector
						1	ı			
							ı			




W/O:			W	ORK ORDER CHANG	ES							
DATE	STEP	PRO	CEDURE CH	ANGE	f	Ву	Date	City	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
		•						1	Prod Wgr	<u> </u>		
			<del></del>									
Part No	; 	PAR #:	Fault Ca	tegory:	_ NCR:	Yes N	lo <b>DQA</b> :		Date:			
	Re	esolution:	Disposit	ion:	QA: N	/C Clo	sed:					
NCR:		\	WORK OR	DER NON-CONFORM	ANCE (	NCR)						
DATE	STEP	Description of NC		to the transfer of the second	tion B		Verifica	ion	Approval	Approval		
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section			QC Inspector		
								1				
<del></del>												
	}								į			




#### **Dart Aerospace Ltd** W/O: **WORK ORDER CHANGES** Approval **Approval** DATE STEP PROCEDURE CHANGE By Qtv **Date** Chief Eng / QC Inspector Prod Mgr Part No: \_\_\_\_\_\_ PAR #: \_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_ Date: \_\_\_\_ Resolution: \_\_\_\_\_ Disposition: \_\_\_\_ QA: N/C Closed: \_\_\_\_ Date: \_\_\_\_ WORK ORDER NON-CONFORMANCE (NCR) NCR: **Corrective Action** Section B **Description of NC Verification Approval Approval STEP** DATE Sign & **Action Description** Initial Section A Section C Chief Eng QC Inspector Date Chief Eng Chief Eng



W/O:			W	ORK ORDER CHANG	ES	-			•
DATE	STEP	PR	OCEDURE CHA	ANGE	Ву	Date	Qt	Approval Chief Eng / Prod Mgr	Approval QC Inspector
<u>u,                                      </u>									
		•						E	
Part No	:	PAR #:	Fault Cate	egory:	_ NCR: Yes	No <b>DQ</b>	\:	Date: _	
	Re	esolution:	Disposition	on:	_ QA: N/C (	Closed:		Date: _	
NCR:			WORK ORD	ER NON-CONFORMA	ANCE (NC	R)			
	STEP	Description of NC		Corrective Action Section		Verific	atibi	n Approval	Approval
	SILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	&   Section	on C	Chief Eng	QC Inspector
							1		
******									
						:			i i
				7. 4			-		




W/O:			W	ORK ORDER CHANC	GES					, .
DATE	STEP	PRO	OCEDURE CH	ANGE	В	у	Date	Qty	Approval Chief Eng /	Approval QC Inspector
		W							Prod Mgr	
								1		
				**************************************				1		
Part No	:	PAR #:	Fault Cate	egory:	_ NCR: `	Yes N	lo <b>DQA</b> :		_ Date: _	
	Re	solution:	Disposition	on:	QA: N/	C Clo	sed:		Date: _	
NCR:			WORK ORE	ER NON-CONFORM	ANCE (I	VCR)				
	STEP	Description of NC			tion B		Verifica	ion	Approval	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng		ign & Date	Section		Chief Eng	QC Inspector
•										
	1		1 1				1 .		1	1



Dart Aerospace L	.td
------------------	-----

W/O:			W	ORK ORDER CHA	NGES					•		
DATE	STEP	PRO	CEDURE CH	ANGE		Ву	Date	City	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
						i		<u> </u>	Prod Mgr	<u>'</u>		
								1				
Part No	) <b>:</b>	PAR #:	Fault Cat	tegory:	NC	R: Yes	No <b>DQA</b>		Date:			
	Resolution:		Dispositi	on:	QA	: N/C CI	osed:		Date:			
NCR:		N.	WORK ORI	DER NON-CONFO	RMANCE	(NCF	R)					
DATE	STEP	Description of NC		Corrective Action	Section B		Verifica	ion	Approval	Approval		
DAIL	SIEF	Section A	Initial Chief Eng	Action Descript Chief Eng	ion	Sign 8 Date	Section	С	Chief Eng	QC Inspector		
				100								
										]		
		\$ 				ļ.				ļ		
	1	1	1			1			1	1		



W/O:			WO	RK ORDER CHANG	GES			ı		·
DATE STEP		PRO	OCEDURE CHAN	IGE		Ву	Date	City	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cated	orv:	NCR	: Yes 1	lo DQA:		Date:	
		solution:								
NCR:		,	WORK ORDE	R NON-CONFORM	ANCE	(NCR)	)			
DATE	STEP	Description of NC			ction B	verificat			Approval	Approval
		Section A	Chief Eng	Action Description Chief Eng		Date	Section C		Chief Eng	QC Inspector
· · · · · · · · · · · · · · · · · · ·									·	

Work Order:	60303
Part Number:	D4132-3
	Page 1 of 1
	Work Order: Part Number:

# FIRST ARTICLE INSPECTION CHECKLIST

X	First Article		Prototype
---	---------------	--	-----------

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
Ø 0.31	+0.012-0.001	0.32	<b>V</b>		VWV	
0.34	+1-0.030	0.36	V	#	VLIN	
0.34	+1-0.030	0.36	<b>V</b>		VerN	
28.33	+1-0.030	28.33	<b>√</b>		MIT	
7,29	+1-0.030	7.29	V	<b> </b>	M,T	
16.54	+1-0.030	16.54	<b>V</b>		M.T	
1.92	+1-0.030	1.92	J		MIT	
11.92	H-0.030	11.92	· /		MT	·
21.90	+1-0-030	21.92	V		MI	
5.31	+1-0.030	531	V		M.T.	
		-				
				<u> </u>		
				<u> </u>		
						÷.
					·	

Measured by:	ml. ml	Audited by:	8	Prototype Approval:	N/A
Date:		Date:	10/02/14	Date:	N/A
Date	10.01.74		190717	Pavised by	Annroved

Rev	Date	Change	Revised by	Approved
Α		New Issue	KJ/JLM	<u> </u>